Format No: CP/TF/01

TEST REPORT ON COARSE AGGREGATES

Lab ID	:	**CP-2018-02-26-09** **Date: 01-03-18**
Customer	:	Assistant Executive Engineer, Dasarahalli Sub division, BBMP, Bangalore.
Address	:	Dasarahalli Sub division, BBMP, Bangalore.
Project Name	:	Providing and sinking of borewells, pump, motor and water supply lines in ward no.14 Bagalagunte.
Agency	:	Technical Manager (West), KRIDL, Project Implementation Unit, No.280, 59th cross, 17th 'C' Main road, 3rd 'Y' Block, Rajajinagar, Bangalore-560010.
Customer's Reference	:	BBMP/EE/DD/WO/121/2017-18
Source of Sample	:	Sample supplied by Agency
Sample condition	:	Satisfactory
Date of Receipt	:	26-02-18
Sample ID No	:	2018-02-26-09 /02(a)
Sample Type	:	40mm down size coarse aggregate
Reference to BIS codes	:	IS: 383:2016 (Specification for Coarse and fine Aggregates) IS: 2386 :1963(Part - 1,3,4) RA2011 IS 2386 Part 1: Particle Size and Shape IS 2386 Part 3: Specific gravity, Density, Voids,Water Absorption IS 2386 Part 4: Mechanical Properties
Date of test	:	26-02-18

SIEVE ANALYSIS (PARTICLE SIZE DISTRIBUTION) OF 40MM DOWN COARSE AGGREGATE:

Total weight taken : 15000 grams

Sample No.	Sieve No.	Weight Retained in gms	Cumulative Weight Retained in gms	% Cumulative Weight Retained	% Passing	Required as per IS 383:2016
1	80 mm	0	0	0.0	100	100
2	40 mm	322	322	2.1	97.9	90-100
3	20 mm	5643	5965	39.8	60.2	30-70
4	10 mm	4663	10628	70.9	29.1	10-35
5	4.75 mm	4025	14653	97.7	2.3	0-5
6	Pan	347	15000	100.0	0	---

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬೆಂಗಳೂರು

CIVIL PRO BANGALORE Sig..... Date.....

M : 9972924526 | Tel : +91 80-23444801 | e...rechan6630@yahoo.co.in, civilproexperts@gmail.com